Appendix E3 – Public Participation

Middle/Lower Bynum Run Assessment

Property Owner and Public Input Comments

Lower Bynum Run More Information

Lower Bynum Run Stream Study

Harford County Public Works would like your input on the findings of the Lower Bynum Run Stream Study. Please use the form below to provide your input either through filling the comment section or by uploading your notes.

First Name	steve
Last Name	kinnear
Address	316 bright oaks drive
City	bel air
State	MD
Zip Code	21015
Phone Number	410-670-3924
Email Address	rskdmk@gmail.com
Comments (optional)	quite extensive study - tough read for lay folks - ha. but much appreciated assessment. received post card today with links to read and comment. i live in the community of bright oaks (singles with a stream right behind my house running from royal oaks drive through the other side of the development under bright oaks drive towards community of hunters run) and could not find anything in the study on that stream or any stream running through the original bright oaks community (got close in section 5.5.6). it is my understanding that ward properties still owns the land and stream area, but really don't want it any more. any help in understanding how we are affected within our community would be appreciated. thank you
Upload your notes, comments, photos, etc. (optional)	Field not completed.

Lower Bynum Run More Information

Lower Bynum Run Stream Study

Harford County Public Works would like your input on the findings of the Lower Bynum Run Stream Study. Please use the form below to provide your input either through filling the comment section or by uploading your notes.

First Name	Bill
Last Name	Myers
Address	1240 Chateau Green Court
City	BelAir
State	MD
Zip Code	21015
Phone Number	410-803-1399
Email Address	willmyers24@gmail.com
Comments (optional)	We have major issues from he stream behind our house. On P 46 of Appendices it is indicated that something could not be found during a field investigation. I would be willing to share pictures of the years that have been shared before. We definitely need help here
Upload your notes, comments, photos, etc. (optional)	Field not completed.

Lower Bynum Run More Information

Lower Bynum Run Stream Study

First Name	Megan
Last Name	McGraw
Address	2200 GELDING WAY
City	BEL AIR

State	MD
Zip Code	21015-8924
Phone Number	4105692778
Email Address	meganmcgraw33@gmail.com
Comments (optional)	Thank you for informing the public of this. I live right by "outfall 67" and I can tell you that is a popular spot with the neighborhood to throw rocks in the creek and to check out nature. Any maintenance would be appreciated.
Upload your notes, comments, photos, etc. (optional)	Field not completed.

Lower Bynum Run More Information

Lower Bynum Run Stream Study

First Name	phil
Last Name	kershner
Address	315 sedgefield court
City	bel air
State	MD
Zip Code	21015
Phone Number	14438579017
Email Address	pkershner54@yahoo.com
Comments (optional)	We have many concerns regarding the bioretention/sand project:
	1. Decreased resale value of our home where we have lived for the past 27 years.
	2. The location appears to be located extremely close to our

house.

- 3, Health concerns due to mosquitoes and other pests breeding in standing pond water.
- 4. Assurance of proper and frequent maintenance to prevent algae overgrowth and unpleasant odor.
- 5. Appearance that detracts from our beautiful community.
- 6. Damage to our property from heavy equipment needed for the project.

Upload your notes, comments, photos, etc. (optional)

Field not completed.

Lower Bynum Run More Information

Lower Bynum Run Stream Study

First Name	Robert
Last Name	Bernhards
Address	748 Dowers Rd
City	Abingdon
State	Maryland
Zip Code	21009
Phone Number	2024132521
Email Address	coryb34@vt.edu
Comments (optional)	Strongly recommend redesigning the stream at Outfall 185. During storms that produce heavy rainfall, the retention pond system is overrun causing extremely large amounts of water to rush into the stream which cannot handle the massive influx. This results in flooding of the walking bridge, path, and neighboring field. It also causes substantial erosion of the stream beds.

Upload your notes, comments, photos, etc. (optional)

Field not completed.

Lower Bynum Run More Information

Lower Bynum Run Stream Study

Harford County Public Works would like your input on the findings of the Lower Bynum Run Stream Study. Please use the form below to provide your input either through filling the comment section or by uploading your notes.

First Name	Charles
Last Name	Fico
Address	507 Cedar Hill Court
City	Bel Air
State	MD
Zip Code	21015
Phone Number	4437189656
Email Address	charles.fico@gmail.com
Comments (optional)	Concerning SWM000342, there is a restoration proposed to move from an extended detention dry pond to a submerged gravel wetland. I am a member of the HOA board and our small community currently maintains and upkeep's the property. Can someone contact us to further discuss the impact to our neighborhood. A couple of question that come up immediately: Would the county take over upkeep? Who would be responsible for covering the conversion?
Upload your notes, comments, photos, etc. (optional)	Field not completed.

Lower Bynum Run More Information

Lower Bynum Run Stream Study

Harford County Public Works would like your input on the findings of the Lower Bynum Run Stream Study. Please use the form below to provide your input either through filling the comment section or by uploading your notes.

First Name	Eric
Last Name	Southern
Address	3703 Misty Valley CT
City	Abingdon
State	MD
Zip Code	21009
Phone Number	410-612-0160
Email Address	robineric@earthlink.net
Comments (optional)	Hidden Stream crosses over Hidden Stream Dr. Before the developer built the neighborhood, the stream ran free and clear for centuries without any required maintenance. Seems to be a perceptual waste of money.
Upload your notes, comments, photos, etc. (optional)	Field not completed.

Lower Bynum Run More Information

Lower Bynum Run Stream Study

First Name	Jamie
Last Name	Martin Wilson
Address	903 Long Bar Harbor Rd
City	Abingdon
State	MD

Zip Code	21009
Phone Number	4106761224
Email Address	jamiemartinwilson@gmail.com
Comments (optional)	Field not completed.
Upload your notes, comments, photos, etc. (optional)	Field not completed.

Lower Bynum Run More Information

Lower Bynum Run Stream Study

Harford County Public Works would like your input on the findings of the Lower Bynum Run Stream Study. Please use the form below to provide your input either through filling the comment section or by uploading your notes.

First Name	Dawn
Last Name	Cullum
Address	911 Deer Court
City	Abingdon
State	MD
Zip Code	21009
Phone Number	4436192864
Email Address	dcullum57@gmail.com
Comments (optional)	I would like to see photos on how it should or would look when done. Are chemicals going to be put down so that the animals or snakes rats and other pest will not come up in our yards.
Upload your notes, comments, photos, etc. (optional)	Field not completed.

Lower Bynum Run More Information

Lower Bynum Run Stream Study

First Name	Stacy
Last Name	Smith
Address	210 Royal Oak Drive
City	Bel Air
State	MD
Zip Code	21015
Phone Number	4432520233
Email Address	stacysmith299@gmail.com
Comments (optional)	Thank you for sharing this study.
Upload your notes, comments, photos, etc. (optional)	Field not completed.